




## REPLACEMENT PARTS LIST

# **Single Zone Ductless Mini-Split with Inverter Technology**

A-SSP12SA-0

# EXPLODED VIEW



## REPLACEMENT PARTS

| Location | Part Name                          | Quantity | Part No.       |
|----------|------------------------------------|----------|----------------|
| 2        | Condenser assembly                 | 1.0      | 15822000009658 |
| 4        | Chassis assembly                   | 1.0      | 12222000013427 |
| 5        | Right side plate                   | 1.0      | 12222000012141 |
| 6        | Handle                             | 1.0      | 12222000010966 |
| 7        | Water collector                    | 1.0      | 12122000007150 |
| 8        | Front panel assembly               | 1.0      | 12222000A06310 |
| 8.1      | Air outlet grille                  | 1.0      | 12222000015025 |
| 8.2      | Front panel                        | 1.0      | 12222000A06311 |
| 9        | Top cover                          | 1.0      | 12222000014305 |
| 10       | Axial flow fan                     | 1.0      | 12100105000821 |
| 11       | Motor                              | 1.0      | 11002015020053 |
| 12       | Motor bracket                      | 1.0      | 12222000012390 |
| 13       | Left supporter                     | 1.0      | 12222000012135 |
| 14       | Partition board                    | 1.0      | 12222000013428 |
| 17       | Terminal block                     | 1.0      | 17400401006456 |
| 18       | Supporter board                    | 1.0      | 12222000019881 |
| 20       | 4-ways valve or Gas valve assembly | 1.0      | 15422000025728 |
| 20.1     | Gas valve                          | 1.0      | 15500204000665 |
| 20.2     | 4-way valve                        | 1.0      | 15500216002563 |
| 20.3     | Valve plate                        | 1.0      | 12222200005738 |
| 20.4     | Muffler assembly                   | 1.0      | 15122000030139 |
| 21       | High pressure valve assembly       | 1.0      | 15422000024078 |
| 21.1     | High pressure valve                | 1.0      | 15500208000028 |
| 21.2     | Capillary                          | 1.0      | 15122000011919 |
| 22       | Compressor                         | 1.0      | 11103020005082 |
| 24       | Copper nut                         | 1.0      | 15500406000016 |
| 24       | Copper nut                         | 1.0      | 15500406000010 |
| 28       | Electronic control box assembly    | 1.0      | 17222000043604 |
| 28.1     | Electrical installation plate      | 1.0      | 12122000030601 |
| 28.3     | Electronic installing box assembly | 1.0      | 12122000030602 |
| 29       | Combination sensor                 | 1.0      | 11201007007503 |
| 33       | Outdoor unit trademark             | 1.0      | 16000201001228 |
| 40       | Crankcase electric heater          | 1.0      | 17402001000559 |
| 41       | Electric heater of chassis         | 1.0      | 17402002000465 |
| 50       | Rear Grille                        | 1.0      | 12222000012385 |
| 51       | Reactor                            | 1.0      | 17400306001263 |
| 99       | Compressor connection cable        | 1.0      | 17401203012697 |

Due to ongoing product improvements, specifications and dimensions are subject to change and correction without notice or incurring obligations. Determining the application and suitability for use of any product is the responsibility of the installer. Additionally, the installer is responsible for verifying dimensional data on the actual product prior to beginning any installation preparations.

Incentive and rebate programs have precise requirements as to product performance and certification. All products meet applicable regulations in effect on date of manufacture; however, certifications are not necessarily granted for the life of a product.

Therefore, it is the responsibility of the applicant to determine whether a specific model qualifies for these incentive/rebate programs.



1900 Wellworth Avenue • Jackson, MI 49203 • 517-787-2100